

A5

location; decrementing the toner level register for the print engine at the printing location if the accumulated value is less than or equal to the toner level of the print engine; and sending the print job to the print engine at the printing location for rendering.—

REMARKS

Please charge any additional fees or deficiencies in fees or credit any overpayment to Deposit Account No. 20-0780/TRSY-25,474 of HOWISON, CHAUZA, THOMA, HANDLEY & ARNOTT, L.L.P.

Respectfully submitted,

HOWISON, SHAUZA, THOMA, HANDLEY & ARNOTT, L.L.P.

Attorneys for Applicants

Gregory M. Howison

Registration No. 30,646

GMH/jk P.O. Box 741715 Dallas, Texas 75374-1715 972/479-0462 March 13, 2001